








ULINE H-1562 MANAGER'S CHAIR

1-800-295-5510
uline.com



PARTS

- | | | | | | |
|---|---|-----------------|---|---|--------------------------|
| ① |  | Small Bolt x 4 | ④ |  | Wide Washers x 10 |
| ② |  | Large Bolt x 6 | ⑤ |  | Thin Washers x 3 |
| ③ |  | Square Bolt x 3 | ⑥ |  | Allen Wrenches (2 sizes) |

ASSEMBLY INSTRUCTIONS

- Use three large bolts and three wide washers to secure each arm on underside of chair base. (See Figure 1)
- Use four small bolts and four wide washers to secure seat mount assembly. (See Figure 2)
- Align holes on chair back with holes in the seat mount assembly. (See Figure 3)
- Use allen wrench to secure chair back with three square bolts and three thin washers.
- Slide five casters into ends of wheel base. (See Figure 4)
- Attach seat post to top of wheel base.
- Place assembled seat on top of seat post. (See Figure 5)

