

ULINE H-915
INDUSTRIAL HEAT GUN

1-800-295-5510
uline.com



TROUBLESHOOTING

OPERATING ISSUE	RECOMMENDATIONS
Gun is not turning on.	If the gun has been used recently the internal thermostat may be keeping the gun from turning on. Allow the gun to cool for 20-30 minutes and try again.
Gun is blowing only cool air.	Adjust the dial on the back of the unit.